
































CM79535



A  X2	B 25mm  X4	C  X2	D  X2	E 16mm  X4
F 60mm  X1	G  X1	H 4mm  X1	I 5mm  X1	J  X1
1  X1	2  X1	3  X1	4  X1	5  X1
6  X1	7  X1	8  X1	9  X1	

1. 	2. 	3.  Do not tighten the screws	4. 
--	--	--	--

5. 	6.  Tighten the screws	7.  Tighten the screws	
---	---	--	---

8. 	9. 	
---	---	---